

Insulated pins on plug tops

This information sheet explains why pins on electrical plugs must be insulated.


As a general rule, all electrical appliances and equipment being offered for sale or hire must comply with the 'insulated pins' requirement. However, exceptions apply for plugs rated at 20 Amps and above (see AS/NZS 3112).

A number of fatalities and incidents have been recorded in which thin metallic items (for example, slats of metal blinds) have contacted the active pins of plugs that were not fully engaged in socket outlets.

To counter this risk, live pins (active and neutral) on 240 volt plug tops and equipment with integral live pins must be insulated for a prescribed length of the pin in accordance with AS/NZS 3112. This means only the tips of the pins engage with the live parts of sockets.

Implementation of this safety initiative commenced during 2000, with a nationally agreed compliance date of 3 April 2005.

Manufacturers, importers, distributors, agents, retailers and hirers are reminded that it is a breach of the *Electricity Act 1945* if plugs without insulated pins are sold or hired or offered for sale or hire.



An example of insulated pins on a plug top.

Note: Building and Energy inspectors carry out inspections in the marketplace to ensure the requirements are met.

Disclaimer – The information contained in this fact sheet is provided as general information and a guide only. It should not be relied upon as legal advice or as an accurate statement of the relevant legislation provisions. If you are uncertain as to your legal obligations, you should obtain independent legal advice.

Building and Energy

Department of Mines, Industry Regulation and Safety
08 6251 1900

8.30am – 4.30pm

Level 1 Mason Bird Building

303 Sevenoaks Street (entrance Grose Avenue)

Cannington Western Australia 6107

M: **Locked Bag 100, East Perth WA 6892**

W: www.dmirs.wa.gov.au/building-and-energy

E: be.energy@dmirs.wa.gov.au

Regional Offices

Goldfields/Esperance (08) 9021 9494

Great Southern (08) 9842 8366

Kimberley (08) 9191 8400

Mid-West (08) 9920 9800

North-West (08) 9185 0900

South-West (08) 9722 2888

National Relay Service: 13 36 77

Translating and Interpreting Service (TIS): 13 14 50

This publication is available in other formats on request to assist people with special needs.